Suzanne Steab - April 2011 Inspection Report

From:

Karl Houskeeper

To:

Iroberts@archcoal.com; mdavis@archcoal.com

Date:

5/4/2011 3:29 PM

Subject:

April 2011 Inspection Report

CC:

ANGELANANCE@utah.gov; DARONHADDOCK@utah.gov; SUZANNESTEAB@utah.gov

Attachments: SUFCO February 2011.pdf

Mike/Leland,

Attached is the April 2011 inspection report for SUFCO.

Thanks,

Karl

P.S. It appears that in June you will have a new inspector. Appreciate working with you and our paths will probably pass again in the future.



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Representativ	es Present During the Inspection:
Company	Leland Roberts
OGM	Karl Houskeeper

Inspection Report

Permit Number:	C0410002			
Inspection Type:	PARTIAL			
Inspection Date:	Tuesday, February 08, 2011			
Start Date/Time:	2/8/2011 5:45:00 AM			
End Date/Time:	2/8/2011 2:00:00 PM			
Last Inspection:	Wednesday, January 12, 2011			

Inspector: Karl Houskeeper,

Weather: Overcast/Snowing, Temp. 19 Deg. F.

InspectionID Report Number: 2639

Accepted by: jhelfric 2/9/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: SUFCO MINE

Address: 597 SOUTH SR24, SALINA UT 84654

County: SEVIER

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages	Mineral Ownership	Types of Operations		
27,605.17 Total Permitted	✓ Federal	✓ Underground		
48.43 Total Disturbed	State	Surface		
Phase I	County	Loadout		
Phase II	☐ Fee	Processing		
Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Date

Tuesday, Febru

ANK SAME HERE

ng.

Inspector ID Number: 49

Permit Number: C0410002 Inspection Type: PARTIAL

Inspection Date: Tuesday, February 08, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 b. For PARTIAL inspections check only the elements evaluated.
 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	Y		Y	(7)
3.	Topsoil				[]
4.a	Hydrologic Balance: Diversions	: 1			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		. :		
4.c	Hydrologic Balance: Other Sediment Control Measures		(111	D
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Efficient Limitations	1		D	
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches		[1] ()		[]
7.	Coal Mine Waste, Refuse Piles, Impoundments	Y			# 1
8.	Noncoal Waste	✓.		Ø.	
9.	Protection of Fish, Wildlife and Related Environmental Issues	F-13			£111
10.	Slides and Other Damage		1 ²² 1		Ü
11.	Contemporaneous Reclamation	[]	1.1		
12.	Backfilling And Grading)		\Box	
13.	Revegetation	,		(1)	
14.	Subsidence Control	= 1	()		
15.	Cessation of Operations	i			
16.a	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls	: '}			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	~		y	
19.	AVS Check	i i			[]
20.	Air Quality Permit		Ü		
21.	Bonding and Insurance				. 🗆
22.	Other				

Permit Number: C0410002

Inspection Continuation Sheet

Inspection Type: PARTIAL

Inspection Date: Tuesday, February 08, 2011

Page 3 of 3

2. Signs and Markers

Mine identification signs were observed at the refuse pile and main facilities. The signs contain the proper information and are located at a point of access from the public.

8. Noncoal Waste

Noncoal waste is being stored in the approved site in a controlled manner.

18. Support Facilities, Utility Installations

Portal construction is still taking place. Plans are being modified and will be submitted to the Division through a permit amendment.